



Product Change Notification

106780 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106780 - 00
Change Title: SR1450, PCN 106780-00, Product Material, Class2: Flash Part of SCSI Hot-Swap Backplane is Being Replaced
Date of Publication: September 18, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Oct 18, 2006
Date of First Availability of Post-Conversion Material:	Oct 18, 2006

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

A change is being made to the SCSI Hot-Swap Backplane(HSBP) used in the Intel Server Chassis SR1450. The change is to replace the flash part of the SCSI HSBP with other flash part, since current flash part is End-Of-Life(EOL). The PBA of the SCSI HSBP is rolled from C88317-303 to C88317-304. The SCSI Hot-Swap Controller(HSC) firmware on the SCSI HSBP is updated to version 1.03. The Boot code of the SCSI HSC firmware is changed to support the new flash part.

Customer Impact of Change and Recommended Action:

The instructions for the customer to update the SCSI HSC firmware:

- If using the software utility "FWPIAUPD.exe" released with the SCSI HSC firmware to update the SCSI HSC firmware, any version of the SCSI HSC firmware can be updated on any PBA of the SCSI HSBP. Because only the Operational code can be updated by this utility. The Boot code can not be updated by this utility.
- If using other utilities or devices that can update both the Boot code and the Operational code(e.g. a flash programmer) to update the SCSI HSC firmware, the correct version of the SCSI HSC firmware must be taken for the particular PBA of the SCSI HSBP. For the SCSI HSBP with the PBA C88317-304 or later, the SCSI HSC firmware version 1.03 or later must be taken. For the SCSI HSBP with the PBA C88317-303 or earlier, the SCSI HSC firmware version 1.00 or earlier must be taken.

Please also refer to the release notes of the SCSI HSC firmware.

Intel anticipates no other customer impact for this change. Evaluate when available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
A1450SCSIKIT	881837	D54221-002	C88317-303	A1450SCSIKIT	881837	D54221-003	C88317-304

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

September 18, 2006

Revision Number:

00

Reason:

Originally Published PCN