



# Product Change Notification

## 104603 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 104603 - 00  
**Change Title:** SR1400, SR2400 SATA Backplane Kits, FYI,  
Class 2 - Firmware Update,  
**Date of Publication:** November 24, 2004

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Software

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Dec 27, 2004
---	--------------

## Description of Change to the Customer:

The HSC firmware has been updated. The firmware is changing from revision 1.06 to 1.08. Changes to the firmware include the following:

1. Changed the default event receiver from 0x20 to 0xFF. This will prevent the HSC from accessing the BMC in mBMC platforms when an event is generated.
2. Fixed a problem where the Set Sensor Event Enable command did not support the disable/enable event and scanning bit. The overriding control is the Sensor Initialization (byte 11) bits 0,1,6,7 in the SDRR. The bits 6 & 7 are used by the enable/disable control function. If not set in the SDRR the control function will not work correctly. This also fixes the "Get Sensor Event Status" problem where only 2 bytes were returned. Now returns up to 6 bytes depending on sensor type.

## Customer Impact of Change and Recommended Action:

Low Impact. Customers should evaluate when available.

## Products Affected / Intel Ordering Codes:

### Component Product Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
A1400SATAKIT	857010	857010	C50061-001	C50061-002	C53564-202	C53564-203
A2400SATAKIT	857013	857013	C55985-001	C55985-002	C53574-302	C53574-303

## Reference Documents / Attachments:

Document:

Location #:

## PCN Revision History:

Date of Revision:

November 24, 2004

Revision Number:

00

Reason:

Originally Published PCN