



Product Change Notification

104943 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104943 - 02
Change Title: D915POM, PCN 104943-02, FFF, chipset stepping, BIOS, gold plated RCA connector
Date of Publication: March 24, 2005

Type of Change Notification:
FFF - (Form-Fit-Function)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 11, 2005
---	--------------

Description of Change to the Customer:

1. Change the 915P Express Chipset Memory Controller Hub (MCH) component from B-1 stepping to C-2 stepping. This stepping change is required to ensure component supply availability to support manufacturing. The Product Change Notice for the chipset change is available at <http://developer.intel.com/design/pcn/Chipsets/D0104532.pdf>
2. Change the RCA connectors at locations J9G1 and J9G2 from silver plating to gold plating so that the RCA connectors match the RCA connector gold plating on the system tv-tuner cards.
3. Add BIOS version OM91510J.86A.0405.

Customer Impact of Change and Recommended Action:

This board change is expected to cause a change to the Microsoft* Windows* operating system's software driver stack. Customer's can prepare for the change by building a new software image based on BIOS version OM91510J.86A.0405 that is available for download at http://developer.intel.com/design/motherbd/om/om_bios.htm.

These hardware changes are being thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
OEMD915POMS2	866474	866474	C85587-304	C85587-305	C85589-304	C85589-305
SD915POMS2	868096	868096	C85587-304	C85587-305	C85589-304	C85589-305

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

March 18, 2005

00

Originally Published PCN

March 18, 2005

01

Delete removal of unused PCI connector

March 24, 2005

02

New BIOS addition