



Product Change Notification

105795 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105795 - 01
Change Title: D945PAWLK, PCN 105795-01, FFF, Gigabit LAN controller conversion, bios update
Date of Publication: January 23, 2006

Type of Change Notification:
FFF - (Form-Fit-Function)

Key Characteristics of the Change:
Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Feb 02, 2006
---	--------------

Description of Change to the Customer:

1. Gigabit LAN controller change from the Intel® 82573V Gigabit Ethernet Controller to the Intel® 82573LS Gigabit Ethernet Controller. The LAN image will be changed accordingly as well.
2. Update BIOS to version SN94510J.86A.0057. Please refer to the BIOS release notes for more information on the BIOS changes.

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional hardware qualification of these changes on platforms received from Intel.

These board changes are expected to cause a change to the Microsoft* Windows* operating system's software driver stack. Please ensure that Intel® PRO Network Connections LAN driver version 10.1 and above is used. Please validate OS image for potential changes.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BLKD945PAWLK 869592	869592	869592	C99569-502	C99569-503	C99570-502	C99570-503
BOXD945PAWLK 869591	869591	869591	C99569-502	C99569-503	C99570-502	C99570-503

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 29, 2005	00	Originally Published PCN
January 23, 2006	01	Change 82573L to 82573LS, change implementation date