



# Product Change Notification

## 104041 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geography location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 104041 - 00  
**Change Title:** D845GVSH, PCN 104041-00, FYI, Front Panel Mic Fix  
**Date of Publication:** April 15, 2004

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Apr 26, 2004
---	--------------

## Description of Change to the Customer:

1) Add 3.3k MIC biasing resistor to R6A6. This fixes issue with Front Panel MIC no audio output and is needed to improve board manufacturability.

## Customer Impact of Change and Recommended Action:

This board change is not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack.

These hardware changes are being thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers. DPSD is not recommending additional qualification of these changes on platforms received from Intel.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Pre-Change TA or AA	Post-Change TA or AA
LAD845GVSHPL	859008	C55654-305	C55654-306

## PCN Revision History:

<b>Date of Revision:</b> April 15, 2004	<b>Revision Number:</b> 00	<b>Reason:</b> Originally Published PCN
--	-------------------------------	--

