



Product Change Notification

104886 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104886 - 01
Change Title: SE7520JR2, PCN 104886-01, FYI, Class 1;
Update Board to BIOS P07 and FRU/SDR
version 6.6.1
Date of Publication: March 07, 2005

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Software

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 18, 2005
---	--------------

Description of Change to the Customer:

Updating board BIOS to P07 and FRU/SDR to version 6.6.1. See BIOS release notes and FRU/SDR release notes for details of the changes. Update Attention Document in the Intel Box Boards to correct URL location, revise the Memory Support information and update the Intel Server Management information.

Customer Impact of Change and Recommended Action:

Intel anticipates no customer impact for this change. Evaluate when available.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BJRDDR1BB	867823	870221	C66716-503	C66716-504	C53662-503	C53662-504
BJRDDR1SATABB	868003	870229	C69650-404	C69650-405	C53660-404	C53660-405
BJRDDR2BB	861065	870233	C66717-601	C66717-603	C53661-602	C53661-603
BJRDDR2SATABB	863332	870608	C69651-301	C69651-303	C53659-301	C53659-303
SE7520JR2ATAD1	867824	867824	C75151-004	C75151-005	C53660-404	C53660-405
SE7520JR2ATAD2	861066	861066	C75149-004	C75149-005	C53659-302	C53659-303
SE7520JR2SCSID1	867828	867828	C75138-004	C75138-005	C53662-503	C53662-504
SE7520JR2SCSID2	861067	861067	C75210-004	C75210-005	C53661-602	C53661-603

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:

March 2, 2005

March 7, 2005

Revision Number:

00

01

Reason:

Originally Published PCN

Update to Class 1; Add new
MM#'s.