



# Product Change Notification

## 105581 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105581 - 00  
**Change Title:** D945GCZ, PCN 105581-00, FYI, Change config label  
**Date of Publication:** October 13, 2005

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Oct 27, 2005
---	--------------

## Description of Change to the Customer:

Change the config label to fix an error in the label where the BIOS config jumper is at the wrong location. Current label shows the jumper in-between the SATA headers and rear backpanel connectors. In actual fact it is located near the speaker.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BLKD945GCZL	869574	869574	TA D14038-104	TA D14038-105		
BLKD945GCZLKR	869570	869570	TA D14040-104	TA D14040-105		
BLKD945GCZLR	869576	869576	TA D14039-104	TA D14039-105		
BOXD945GCZL	869573	869573	TA D14041-103	TA D14041-104		

<b>Affected Product Code</b>	<b>Pre-Change MM#</b>	<b>Post-Change MM#</b>	<b>Pre-Change TA or AA</b>	<b>Post-Change TA or AA</b>	<b>Pre-Change PBA</b>	<b>Post-Change PBA</b>
BOXD945GCZLKR	869569	869569	TA D14043-105	TA D14043-106		
BOXD945GCZLR	869579	869579	TA D14042-105	TA D14042-106		
LAD945GCZCS	869689	869689	TA D99717-101	TA D99717-102		
LAD945GCZLK	868926	868926	TA D21400-100	TA D21400-101		

**Reference Documents / Attachments:**

**Document:**

**Location #:**

**PCN Revision History:**

**Date of Revision:**

October 13, 2005

**Revision Number:**

00

**Reason:**

Originally Published PCN