



Product Change Notification

103067 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please respond to your distributor.

Copyright © Intel Corporation 2003. Third-party brands and names are the property of their respective owners.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANdesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 103067 - 00
Change Title: D300JCT, PCN 103067-00, FYI, Replace clock buffer to correct erratic and intermittent behavior when running Manufacturing Tests.
Date of Publication: February 25, 2003

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material:	Mar 07, 2003
--	--------------

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

Replace 5 volt clock buffer at location U 26 with 3.3 volt buffer for all new builds of the PC Board Assy. This component change will correct erratic and intermittent behavior when running Manufacturing Tests.

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure there are no functional implications to our customers.
This change has no impact on units in the field.
Customers should modify their databases in order to place orders against the new order codes. See details below.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Pre-Change Product Code	Pre-Change MM#	Post Change Product Code	Post-Change MM#
D300JCTE175	841796	D300JCTE175	853338
D300JCTE175R2U	842365	D300JCTE175R2U	853338
D300JCTE175R2U	843967	D300JCTE175R2U	853338
D300JCTE175R2U	844507	D300JCTE175R2U	853338
D300JCTE175R2U	849321	D300JCTE175R2U	853338
D300JCTE175CNU	852149	D300JCTE175CNU	853337
D300JCTE175	841172	D300JCTE175	853937
D300JCTE175CN	845020	D300JCTE175CN	854004
D300JCTE1120	841171	D300JCTE1120	853948
D300JCTE1120	842258	D300JCTE1120	853948
D300JCTE1120IN	846447	D300JCTE1120IN	853947

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

February 25, 2003

00

Originally Published PCN