



# Product Change Notification

## 103505 - 05

**Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.**

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geography. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.**



# Product Change Notification

**Change Notification #:** 103505 - 05  
**Change Title:** SE7501BR2, BBR2BB, PCN 103505-05, FYI,  
Class 1: Change to BIOS, BMC Firmware,  
FRUSDR, Resource and ISM CDs  
**Date of Publication:** February 20, 2004

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Software

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 05, 2004
<b>Date of First Availability of Post-Conversion Material:</b>	Mar 05, 2004

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

BIOS on the board will be updated from ver P04 to P13.  
BMC firmware on the board will be updated from BMC 1.14 to BMC 1.18.  
FRU/SDR utility on the board will be updated from 5.5.D to 5.5.I.  
Update SE7501BR2 Quick Start User's Guide, and update Attention Sheet.  
Intel Server Management CD included in the SE7501BR2 will be updated from ver 5.5.1 to ver 5.5.7.  
Replace Cable kit (A66329-002) on the SE7501BR2 product code with equivalent kit (A66329-003) which contains 1.5" longer Serial B cable (23.5").

Resource CD included in the SE7501BR2 product code will be updated with the following changes:  
Add Microsoft\* Windows 2003, Red Hat Linux 9.0 and SuSE 8.2 drivers for on-board components.  
Update existing drivers for on-board components.  
Update Server Configuration Wizard with FRUSDR 5.5.I.

## Customer Impact of Change and Recommended Action:

Orders for BBR2BB SKU will need to be submitted using a new MM#.

Board impact and recommendation: The BIOS, BMC firmware and FRU/SDR have changed. Changes may require customer documentation changes and/or customer evaluation upon receipt.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BBR2BB	852887	857552	A84860-505	A84860-506	A95686-505	A95686-506
SE7501BR2	848909	848909	A98206-004	A98206-005	A95686-505	A95686-506

## Reference Documents / Attachments:

**Document:** \_\_\_\_\_ **Location #:** \_\_\_\_\_

## PCN Revision History:

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
July 30, 2003	00	Originally Published PCN
August 27, 2003	01	Update effectivity date and part numbers on Board Products Table
October 14, 2003	02	Updated effectivity date, MM# for BBR2BB product code, BMC and FRUSDR versions.
October 31, 2003	03	Removed ISM CD and PG changes from change list.
December 16, 2003	04	Add back ISM CD change and update effectivity date.
February 20, 2004	05	Change effectivity date