



Product Change Notification

106951 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106951 - 01
Change Title: SHW4URM23 and SHW6URM23, PCN 106951-01, Product Design, CLASS 2: BIOS Update, Reason for Revision: correct top assembly number
Date of Publication: November 05, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Nov 10, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: correct top assembly number

SHW4URM23

Change the MM# from 877218 to 886993
Change the BIOS to P10.1
Change top assembly part number from D35288-006 to D35288-007
Change the main board part number from D22177-553 to D22177-602

SHW6URM23

Change the MM# from 877217 to 886994
Change the BIOS to P10.1
Change top assembly part number from D35290-004 to D35290-005
Change the main board part number from D22177-553 to D22177-602

BIOS 10.1

Correct the bus number for PCI Hot-Plug Slots in P10 BIOS to maintain these numbers are same as former version.

Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA
SHW6URM23 877217	877217	D35290-004	886994	D35290-005
SHW4URM23	877218	D35288-006	886993	D35288-007

877218				
--------	--	--	--	--

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
November 3, 2006	00	Originally Published PCN
November 5, 2006	01	correct top assembly number