



# Product Change Notification

## 106623 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jcb.ijkk@intel.com](mailto:jcb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106623 - 02  
**Change Title:** Intel NetStructure (R) MPCBL0001, PCN 106623-02, Product Design, Incorporated IPMC firmware 1.17 and Replace non-nylok screws with nylok screws, Reason for Revision: Updated with latest change status  
**Date of Publication:** July 05, 2007

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Jan 12, 2007
<b>Date of First Availability of Post-Conversion Material:</b>	Jan 12, 2007

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

### Reason for Revision: Updated with latest change status

1. Implemented IPMC firmware from version 1.17 for MPCBL0001N04/F04.

*IPMC firmware version 1.17 was not programmed on the board as previously notified. However, it has been available from Intel web site, <http://support.intel.com/support/network/computeboards/mpcbl0001/software.htm#firmware>, since July 31, 2006.*

2. A change from a non-RoHS screw with RoHS screw located on the Power Mezzanine Module assembly.

*This change was not correctly stated. The change is actually for replacement of non-nylok screws with nylok screws, implemented in the board TA (top assembly) number as listed below which has been shipping since January 12, 2007.*

## Customer Impact of Change and Recommended Action:

1. Customers should validate the new IPMC firmware.
2. No functional impact. No action recommended.

## Products Affected / Intel Ordering Codes:

Board Products Table					
Product Code	MM#	Pre-Change TA	Post-Change TA	Pre-Change PBA	Post-Change PBA
MPCBL0001N04	855964	C13354-021	C13354-022	C44585-407	C44585-408
MPCBL0001F04	855965	C55360-022	C55360-023	A97017-407	A97017-408

## Reference Documents / Attachments:

**Document:**    **Location #:**

Firmware 1.17 <http://support.intel.com/support/network/computeboards/mpcbl0001/software.htm#firmware>  
Release Notes

## PCN Revision History:

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
August 17, 2006	00	Originally Published PCN
September 11, 2006	01	Ejector handle change not implemented on Non-RoHS MPCBL0001
July 5, 2007	02	Updated with latest change status