



Product Change Notification

105389 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANdesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105389 - 00
Change Title: D945PAW, PCN 105389-00, FYI, CLASS 2:
FAB E CONVERSION, BIOS 0042 AND
BOM FIX FOR SIO
Date of Publication: August 08, 2005

Type of Change Notification:

FYI - (For Your Information)

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 01, 2005
---	--------------

Description of Change to the Customer:

- * FET was moved to correct chassis interference.
- * Lowered the BID to 1Kohm and changed the 1-Watt circuitry to 0ohm and 2.2K.
- * BIOS change to 0042.

Customer Impact of Change and Recommended Action:

Customer may want to validate BIOS changes.
This board change is not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. These hardware changes are being thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes received from Intel.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BLKD945PAWLK 869592	869592	869592	C99569-402	C99569-500	C99570-402 REV03	C99570-500
BOXD945PAWLK 869591	869591	869591	C99569-402	C99569-500	C99570-402 REV03	C99570-500
LAD945PAWLK 868959	868959	868959	C99571-402	C99571-500	C99572-402	C99572-500

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

August 8, 2005

Revision Number:

00

Reason:

Originally Published PCN