



Product Change Notification

104754 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104754 - 00
Change Title: SR2400 & SR2400JR2, FYI, Class 2 - Fan Distribution Board Change
Date of Publication: January 17, 2005

Type of Change Notification:
 FYI - (For Your Information)

Key Characteristics of the Change:
 Product Material

Forecasted Key Milestones:

Customer Must Be Ready To Rcv	Jan 28, 2005
--------------------------------------	--------------

Description of Change to the Customer:

A safety design change is being implemented on the PBA of the fan distribution board. The copper fill area of a trace is being moved to eliminate the current need of using a protective insulator which was put in place to address concerns of a potential short from occurring.

The fan dist. board PBA# is changing from C74974-301 to C74974-302

Customer Impact of Change and Recommended Action:

Intel anticipates no customer impact for this change. Evaluate when available.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
ADR2UEESPRKIT	857585	857585	C56066-001	C56066-002	C74974-301	C74974-302
SJR2USKU07	864821	864821	C79926-001	C79926-002	C74974-301	C74974-302
SR2400	857037	857037	C75268-001	C75268-002	C74974-301	C74974-302
SR2400NA	857228	857228	C75268-001	C75268-002	C74974-301	C74974-302
SR2400SYS	865593	865593	C51956-001	C51956-002	C74974-301	C74974-302
SR2400SYSD2	865605	865605	C75704-001	C75704-002	C74974-301	C74974-302
SR2400SYSD2NA	866080	866080	C75704-001	C75704-002	C74974-301	C74974-302
SR2400SYSNA	865594	865594	C51956-001	C51956-002	C74974-301	C74974-302

PCN Revision History:

Date of Revision: January 17, 2005	Revision Number: 00	Reason: Originally Published PCN
--	-------------------------------	--

