



Product Change Notification

105255 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105255 - 00
Change Title: D915PCY, D915PCM, PCN 105255-00, FFF,
CLASS 2 - NEW CD, BIOS UPDATE &
AUDIO CODEC CONVERSION
Date of Publication: June 23, 2005

Type of Change Notification:
FFF - (Form-Fit-Function)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jul 08, 2005
---	--------------

Description of Change to the Customer:

1. Update bios to version 0035 to support new audio CODEC
2. Use new audio codec to pass latest WHQL requirement
3. Incorporate New CDA for updated audio drivers

Customer Impact of Change and Recommended Action:

These board changes ARE expected to cause a change to the Microsoft* Windows* operating system's software driver stack due to a subsystem vendor ID change. These hardware changes have been thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BLKD915PCML	859809	859809	C64000-206	C64000-207	C66988-206	C66988-207
BLKD915PCY	859812	859812	C64008-303	C64008-304	C66974-303	C66974-304
BLKD915PCYL	859814	859814	C64007-303	C64007-304	C66973-303	C66973-304
BOXD915PCML	859808	859808	C64000-206	C64000-207	C66988-206	C66988-207
BOXD915PCY	859811	859811	C64008-303	C64008-304	C66974-303	C66974-304
BOXD915PCYL	859813	859813	C64007-303	C64007-304	C66973-303	C66973-304
LAD915PCML	859862	859862	C64661-202	C64661-203	C66987-202	C66987-203

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
LAD915PCY	860041	860041	C64010-303	C64010-304	C66976-303	C66976-304
LAD915PCYL	860038	860038	C64009-303	C64009-304	C66975-303	C66975-304

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

June 23, 2005

Revision Number:

00

Reason:

Originally Published PCN