



# Product Change Notification

## 106041 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106041 - 00  
**Change Title:** D945GRW, PCN 106041-00, Product Marking, Minor rev change on silkscreen  
**Date of Publication:** March 09, 2006

## Key Characteristics of the Change:

Product Marking

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 24, 2006
---	--------------

## Description of Change to the Customer:

PCB part number silkscreen change from 316737300305 to 316737300306.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSP is not recommending additional qualification of these changes on platforms received from Intel. These board changes are expected not to cause a change to the Microsoft\* Windows\* operating system's software driver stack.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA
BLKD945GRWLK 876555	876555	876555	D30999-500	D30999-501
BOXD945GRWLK 876556	876556	876556	D30999-500	D30999-501
LAD945GRWLK 877148	877148	877148	D30998-500	D30998-501

**Reference Documents / Attachments:**

**Document:**

**Location #:**

**PCN Revision History:**

**Date of Revision:**

March 9, 2006

**Revision Number:**

00

**Reason:**

Originally Published PCN