



Product Change Notification

106477 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106477 - 00
Change Title: SE7230CA1, PCN 106477-00, Product Design, Class1, Update BIOS in BOM from R14 to R17 to fix some issues.
Date of Publication: July 19, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 01, 2006
---	--------------

Description of Change to the Customer:

- 1.Add the new fan control profile.
- 2.Add Intel OSB Logo .
- 3.Cpu socket Jumper info updated with "J4H1"
- 4.Add Intel new OSB Logo
- 5.Fixed the issue about the event log need to be cleared upon exit from manufacturing mode
- 6.Fixed the issue for ECC error is not logged into SEL with the special test method and Memory.
- 7.Fixed the issue about incomplete IDE controllers detected in manufacturing mode at first boot

Customer Impact of Change and Recommended Action:

Evaluate when received

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BCAHBB 882718	882718	882718	D53438-302	D53438-303	D40857-302	D40857-303
BCAVBB 882773	882773	882773	D54975-302	D54975-303	D53837-302	D53837-303

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:
July 19, 2006

Revision Number:
00

Reason:
Originally Published PCN