



Product Change Notification

107137 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107137 - 00
Change Title: D945GTP, PCN 107137-00, Product Design, Product Improvement
Date of Publication: December 21, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 04, 2007
---	--------------

Description of Change to the Customer:

Product improvement for skus with LAN subsystem using the Intel® 82573E/82573V/82574V Gigabit Ethernet Controller.

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LAD945GTPLKR 868931	868931	97837-303	C97838-303	C97837-304	C97838-304
LAD945GTPLK 868934	868934	97844-305	C97845-306	C97844-306	C97845-306
BLKD945GTPLKR 869549	869549	97837-303	C97838-303	C97837-304	C97838-304
BOXD945GTPLKR 869550	869550	97837-303	C97838-303	C97837-304	C97838-304
LAD945GTPLK2 876656	876656	D36047-303	D36048-303	D36047-304	D36048-304

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:

December 21, 2006

Revision Number:

00

Reason:

Originally Published PCN