



# Product Change Notification

## 105571 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105571 - 01  
**Change Title:** ARIGRACK, PCN 105571-01, FYI, CLASS 2: RIGGINS DESIGN IMPROVEMENTS TO 3U SLIDE RAIL  
**Date of Publication:** December 07, 2005

**Type of Change Notification:**  
FYI - (For Your Information)


**Key Characteristics of the Change:**  
Product Design

## Forecasted Key Milestones:


<b>Date of First Availability of Post-Conversion Material:</b>	Dec 26, 2005
--	--------------

## Description of Change to the Customer:

1. Three embosses added to the sheet metal (can't see in the image, they are under the multi-pin). Function is to hold the multi-pin out farther from the slide rail, which positions the slide rail correctly in a rack cabinet.
2. Plastic swing block moved in this direction to hold the multi-pin better. This was done on both the front and the back of the slide rails. (see image below for change #1 & #2)



3. Material removed from this area of the plastic swing block. All swing blocks on the rails are affected. (see image below)



4. Locking tab added to the plastic sliding block. This prevents the cable management arm from disconnecting unexpectedly. (see image below)



**Customer Impact of Change and Recommended Action:**

Evaluate upon receipt

**Products Affected / Intel Ordering Codes:**

**Component Product Table**

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
ARIGRACK	856670	856670	C54873-003	C54873-004		

**Reference Documents / Attachments:**

Document:

Location #:

**PCN Revision History:**

**Date of Revision:**

**Revision Number:**

**Reason:**

October 7, 2005  
December 7, 2005

00  
01

Originally Published PCN  
Changes are being implemented at a later date. Another change will be added to PCN