



# Product Change Notification

## 105305 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105305 - 01  
**Change Title:** SE7320VP2, PCN 105305-01, FYI, Class 1:  
FAB change to correct Heceta Errata #10 -  
CM93 Sensor Monitoring Issue, Updating  
Server Board BIOS and FRU/SDR, Updating  
the Deployment Toolkit CD, Updating the  
Quick Start Guide  
**Date of Publication:** July 20, 2005

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Product Design

**Forecasted Key Milestones:**

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Sep 09, 2005
---	--------------

**Description of Change to the Customer:**

The following changes will be made on Intel(R) Server Board SE7320VP2.

1. A FAB change will be made to the Intel(R) Server Board SE7320VP2 to correct Heceta Errata #10-CM93 Sensor Monitoring Issue. The change will add a pull up 4.7K ohm resistor and a pull down 10K ohm resistor site to the reset pin of Heceta (U5J1).
2. A new Deployment Toolkit CD will replace version 8.10 of Intel Server Management with version 8.30. See the release notes for details.
3. The server board BIOS will change from BIOS Production 3 to BIOS Production 5. See the release notes for details.
4. The Field Replaceable Unit/Sensor Data Record (FRUSDR) will change from version 1.50 to 1.70 (6.6.H). See the release notes for details.
5. The SE7320VP2 Quick Start Guide will be updated from revision 002 to 003.

**Customer Impact of Change and Recommended Action:**

Customers need to be aware of these changes and should evaluate the changes when available.

**Products Affected / Intel Ordering Codes:**

**Board Products Table**

<b>Affected Product Code</b>	<b>Pre-Change MM#</b>	<b>Post-Change MM#</b>	<b>Pre-Change TA or AA</b>	<b>Post-Change TA or AA</b>	<b>Pre-Change PBA</b>	<b>Post-Change PBA</b>
BVP7320	859199	874905	C77385-605	C77385-701	C63184-605	C63184-701
SE7320VP2	867850	867850	C71271-006	C71271-007	C63184-605	C63184-701

### **Reference Documents / Attachments:**

**Document:**

**Location #:**

### **PCN Revision History:**

**Date of Revision:**

**Revision Number:**

**Reason:**

July 7, 2005

00

Originally Published PCN

July 20, 2005

01

Change BIOS version to P05