



Product Change Notification

111618 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2012. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 111618 – 00

**Change Title: Intel® Server System
R1208GZ4GC, R1304GZ4GC,
R2208GZ4GC, R2308GZ4GC and
R2312GZ4GC4
PCN 111618-00, Product Design,
System Top Cover Updated and
Changing BBU Bracket Length,
Update the BIOS and
Manageability Engine**

Date of Publication: July 23, 2012

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

	Core SKU
Date Customer Must be Ready to Receive Post-Conversion Material:	July 24, 2012

Description of Change to the Customer:

Intel has implemented the following changes at factory:

For Intel® Server System **R1208GZ4GC** and Intel® Server System **R1304GZ4GC:**

1. Updated the top cover to improve fit tolerances.
2. Updated the Quick User's Installation Guide from G31060-003 to G31060-004 with new installation instructions for installing top cover screws.
3. Changed the BBU bracket length to accommodate all system chassis.
4. Update the BIOS from revision 01.01.1002 to 01.02.0005 and update the Manageability Engine (ME) firmware from revision 02.01.05.069 to 02.01.05.091. Please see Technical Advisory TA-0996 for more information.

For Intel® Server System **R2208GZ4GC** and Intel® Server System **R2308GZ4GC:**

1. Updated the top cover to improve fit tolerances.
2. Updated the Quick User's Installation Guide from G31061-003 to G31061-004 with new installation instructions for installing top cover screws

For Intel® Server System **R2312GZ4GC4**

1. Updated the top cover to improve fit tolerances.
2. Updated the Quick User's Installation Guide from G31061-003 to G31061-004 with new installation instructions for installing top cover screws.
3. Update the BIOS from revision 01.01.1002 to 01.02.0005 and update the Manageability Engine (ME) firmware from revision 02.01.05.069 to 02.01.05.091.

Please see Technical Advisory TA-0996 for more information.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers; no action is recommended or required.

Intel recommends that the customer perform a standard level of evaluation as updated BIOS and ME firmware become available.

Products Affected / Intel Ordering Codes:

Core SKU					
Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
R1304GZ4GC	916994	G46822-001	G11481-351	G46822-002	G11481-352
R1208GZ4GC	916995	G46823-001	G11481-351	G46823-002	G11481-352
R2208GZ4GC	917001	G46831-001	G11481-351	G46831-002	G11481-351
R2308GZ4GC	917004	G46826-001	G11481-351	G46826-002	G11481-351
R2312GZ4GC4	921972	G63761-001	G11481-351	G63761-002	G11481-352

PCN Revision History:

Date of Revision:

July 23, 2012

Revision Number:

00

Reason:

Originally Published PCN