



Product Change Notification

107692 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

America's OEM's Contact:

Lester Dimit

Phone:(503) 712-8272

Email: lester.dimit@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at

<http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107692 - 00
Change Title: Intel® Wireless WiFi Link 4965AGN Skus: 4965AGNMJPGN, JPGN0, M1WB, M2WB, RWWB, JPWB; 4965AG_MJPGN (MM#s 886437, 891353, 886704, 886734, 886727, 886732, 886461), PCN 107692-00, Label, Product Label update to JP DSPR # and change WB Insert Documentation.
Date of Publication: June 27, 2007

Key Characteristics of the Change:

Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jul 13, 2007
Date of First Availability of Post-Conversion Material:	Jul 13, 2007

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

This ECO will incorporate the following changes:

1. Incorporate May JP DSPR ID on the 4965AGNMJPGN, JPGN0, JPWB and the 4965AG_MJPGN SKUs, as per JP DSPR Cadence.
2. Remove the regulatory marking for Argentina on the 4965AGNMM1WB SKU.
3. Add instructions to download the latest SW/Drivers to the flyer insert for the 4965AGN WB SKUs. This SW/Driver download fixes a SW issue that affects the JP and RW SKUs.

Customer Impact of Change and Recommended Action:

Customer will receive product with the following changes:

1. May JP DSPR ID updated on the 4965AGNMJPGN, JPGN0, JPWB SKUs, and the 4965AG_MJPGN SKU.

	<u>AGN</u>	<u>AG</u>
New DSPR ID #	4965AGNMJP 003NY061530212 003WY060570212	4965AG_MJP 003NY061530213 003WY060570213

2. The following Regulatory Markings removed from the 4965AGNMM1WB SKU

Country	AGN
Argentina	C-5419 C-5421

3. Instructions to download the latest SW/Drivers added to the flyer insert for the 4965AGN WB SKUs. This SW/Driver download fixes a SW issue that affects the JP and RW SKUs (see below).

NOTE: To ensure that the wireless capability of your system functions in accordance with our product specification, please update your system by installing the 11.1.0.5 software driver fix available at http://downloadcenter.intel.com/Product_Filter.aspx?ProductID=2753. Follow the instructions below:

1. Navigate to http://downloadcenter.intel.com/Product_Filter.aspx?ProductID=2753 .
2. Select the appropriate OS
3. Click on the 11.1.0.5 Driver-only package or complete software package (software and drivers included):
 - a. Driver-only Example: Intel® PRO/Wireless Drivers-Only for Windows* XP [V11.1.0.5_XP_DRIVERS.ZIP]
 - b. Software Application: Intel® PROSet/Wireless Network Connection Software [V11.1.0.5_XP32.EXE]

4. Dash to the TA

Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage and migrate to the post-conversion material as soon as possible.

For your information only. No change to form fit or function. No change to Intel Ordering codes.

Milestone dates are estimates and subject to change based on business and operational conditions.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
4965AGNMJPGN	886437	886437	D73382-008	D73382-009	D65465-006	D65465-006
4965AGNMJPGN0	891353	891353	E11063-001	E11063-002	D65465-006	D65465-006
4965AGNMM1WB	886704	886704	D74675-002	D74675-003	D65465-006	D65465-006
4965AGNMM2WB	886734	886734	D74676-002	D74676-003	D65465-006	D65465-006
4965AGNMRWWB	886727	886727	D74678-001	D74678-002	D65465-006	D65465-006
4965AGNMJPWB	886732	886732	D74679-002	D74679-003	D65465-006	D65465-006
4965AG_MJPGN	886461	886461	D74674-006	D74674-007	D65465-006	D65465-006

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

June 27, 2007

Revision Number:

00

Reason:

Originally Published PCN