



Product Change Notification

102664 - 01

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2002. Third-party brands and names are the property of their respective owners.

Intel, Insight960, Intel386, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Intel GigaBlade, Intel StrataFlash, Intel Xeon™, Intel XScale, Itanium™, OverDrive, Pentium®, Pentium® II Xeon™, Pentium® III Xeon™, Solutions960, LANDesk, Celeron®, FlashFile, i386, i486, i960, iCAT, iCOMP, Intel SingleDriver technology, EtherExpress™, AnyPoint is a trademark or registered trademark of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.

Change Notification #:	# 102664 - 01
Change Title:	D845EBT, PCN, 102664 - rev 01, FYI, BIOS update and HDD LED fix.
Date of PCN Publication:	Friday, August 02, 2002

Type of Change Notification:

FYI (for-your-information)

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material: Aug 07, 2002

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

Updated product to offer more robust hard drive LED operation.

Updated product to BIOS P05.

P05-0007

- Fixed issue where Windows 2000 would reload hardware profile after entering BIOS.
- Fixed issue where in some configurations, USB devices attached to a hub were not detected. BIOS would sometimes fail to detect Full speed USB devices through a USB hub when an unknown USB device (such as USB scanner) was attached to a lower number port on the same hub.
- Made the work-around for 1394 issue more robust by enable Secondary Discard Timer
- Fixed the issue of not being able to wake the system up in S3 using the PING command.
- Set IDE RAID BOOT question to enabled per customer request.

Customer Impact of Change and Recommended Action:

No customer impact, no action needed.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
LAD845EBTS1	847252	847252	A89927-401	A89927-402	A89910-401	A89910-402

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Jul 02, 2002

Aug 02, 2002

Revision Number:

00

01

Reason:

Originally Published PCN

Update after finalizing ECO.