



# Product Change Notification

## 108006 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jcb.ijkk@intel.com](mailto:jcb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 108006 - 00  
**Change Title:** Quality Issue Correction, PCN 108006-00,  
Product Material, SSR212MC2 and  
SSR212MC2R.  
**Date of Publication:** October 15, 2007

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Oct 19, 2007
---	--------------

## Description of Change to the Customer:

To address several quality related issues, the following changes were incorporated on Intel® Storage Server SSR212MC2 and SSR212MC2R:

1. Updated Attention Document to D91601-002.
2. Roll Accessory Kit Dash, Add HDD Carrier LED Labels.
3. Boot drive cables not plugged into the boot drive enclosure. Tracked by TA roll.
4. Boot drive enclosure backplane Torx screws replaced with Philips screws. Tracked by TA roll.
5. Boot drive enclosure mounting screws replaced with new material. Tracked by TA roll.

## Customer Impact of Change and Recommended Action:

Customers should apply the HDD LED labels to all HDD carriers that don't have HDD's installed, plug in the boot drive cables after 2.5" HDD(s) are installed in the boot drive enclosure, and note the Top Assembly (TA) dash number change below.

### Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change Product Code	Post Change MM#	Post Change TA
SSR212MC2	891935	D88964-002	SSR212MC2	891935	D88964-003
SSR212MC2R	891934	D88965-002	SSR212MC2R	891934	D88965-003

Pre Conversion Product Code	Pre Conversion MM#	Post Conversion Product Code	Post Conversion MM#
SSR212MC2NA	892294	SSR212MC2NA	892294
SSR212MC2RNA	892295	SSR212MC2RNA	892295

### Reference Documents / Attachments:

Document:

Location #:

### PCN Revision History:

Date of Revision:

October 15, 2007

Revision Number:

00

Reason:

Originally Published PCN