



# Product Change Notification

## 106703 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jcb.ijkk@intel.com](mailto:jcb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106703 - 02  
**Change Title:** Intel NetStructure (R) MPCBL0001F04Q, MPCBL0001N04Q, PCN 106703-02, Product Material, Replaced non-nylok screws with nylok screws, Reason for Revision: Corrected post-change TA and PBA numbers  
**Date of Publication:** July 23, 2007

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Jan 12, 2007
<b>Date of First Availability of Post-Conversion Material:</b>	Jan 12, 2007

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

### Reason for Revision: Corrected post-change TA and PBA numbers

1. Implemented IPMC firmware from version 1.17 for MPCBL0001N04Q/F04Q.

*IPMC firmware version 1.17 was not programmed on the board as previously notified. However, it has been available from Intel web site, <http://support.intel.com/support/network/computeboards/mpcbl0001/software.htm#firmware>, since July 31, 2006.*

2. A change from a non-RoHS screw with RoHS screw located on the Power Mezzanine Module assembly.

*This change was not correctly stated. There are no non-RoHS screws on MPCBL0001N04Q and MPCBL0001F04Q. The change was actually for replacement of non-nylok screws with nylok screws, implemented since January 12, 2007.*

3. Ejector vendor change and faceplate overlay dimension modification.

*This previously notified change was deferred. Further information will be provided via a new PCN.*

### **Customer Impact of Change and Recommended Action:**

No functional impact. No action recommended.

### **Products Affected / Intel Ordering Codes:**

<b>Board Products Table</b>					
<b>Product Code</b>	<b>MM#</b>	<b>Pre Change TA</b>	<b>Post Change TA</b>	<b>Pre Change PBA</b>	<b>Post Change PBA</b>
MPCBL0001F04Q	875601	D17324-005	D17324-005	D16300-104	D16300-104
MPCBL0001N04Q	875602	D18530-005	D18530-005	D18536-104	D18536-104

### **Reference Documents / Attachments:**

**Document:**    **Location #:**

Firmware 1.17 <http://support.intel.com/support/network/computeboards/mpcbl0001/software.htm#firmware>  
Release Notes

### **PCN Revision History:**

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
August 20, 2006	00	Originally Published PCN
July 5, 2007	01	Updated with latest change status
July 23, 2007	02	Corrected post-change TA and PBA numbers