



# Product Change Notification

## 106242 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106242 - 00  
**Change Title:** D945GRW, PCN 106242-00, Product Design, Bios update  
**Date of Publication:** April 25, 2006

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

|   |              |
|---|--------------|
| <b>Date Customer Must be Ready to Receive Post-Conversion Material:</b> | Apr 29, 2006 |
|---|--------------|

## Description of Change to the Customer:

Update the bios to ME94510M.86A.0074. Please refer to <http://www.intel.com/products/motherboard/d945grw> for the release notes.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes on platforms received from Intel. These board changes are expected not to cause a change to the Microsoft\* Windows\* operating system's software driver stack.

## Products Affected / Intel Ordering Codes:

### Board Products Table

| Affected Product Code | Pre-Change MM# | Post-Change MM# | Pre-Change AA | Post-Change AA |
|-----------------------|----------------|-----------------|---------------|----------------|
| BLKD945GRWLK          | 876555         | 876555          | D30999-501    | D30999-502     |
| BOXD945GRWLK          | 876556         | 876556          | D30999-501    | D30999-502     |
| LAD945GRWLK           | 877148         | 877148          | D30998-501    | D30998-502     |

## Reference Documents / Attachments:

**Document:** **Location #:**

## PCN Revision History:

**Date of Revision:** **Revision Number:** **Reason:**

April 25, 2006

00

Originally Published PCN