Product Change Notification

Change Notification #:	**115772 - 00**
Change Title:	**Intel® NUC Kit w/ 16GB Intel® Optane™ memory, NUC7i3BNHX1, Intel® NUC Kit w/ 16GB Intel® Optane™ memory, NUC7i5BNHX1, Intel® NUC Kit w/ 16GB Intel® Optane™ memory, NUC7i7BNHX1, Intel® NUC Kit, NUC7i3BNH, Intel® NUC Kit, NUC7i3BNK, Intel® NUC Kit, NUC7i5BNH, Intel® NUC Kit, NUC7i5BNK, Intel® NUC Kit, NUC7i7BNH, Intel® NUC Board NUC7i3BNB, Intel® NUC Board NUC7i5BNB, Intel® NUC Board NUC7i7BNB, PCN 115772-00, Product Design, Label, Product Marking, BIOS Update, Marking Addition and labeling update**
Date of Publication:	**August 23, 2017**

Key Characteristics of the Change:

Product Design, Label, Product Marking

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 11, 2017

Description of Change to the Customer:

The Intel® NUC Kit and Intel® NUC Board SKUs listed in the products affected table below will have the following changes.

1. For all SKUs the BIOS will be updated from BNKBL357.86A.0047 to BNKBL357.86A.0049. To access the release notes or get a copy of the BIOS for evaluation, go to http://downloadcenter.intel.com.

2. For the following SKUs the Printed Circuit Board will have the hot port mark added for IEC-62368.

SKUs:
BOXNUC7I3BNK
BOXNUC7I3BNH
BOXNUC7I3BNKL
BOXNUC7I3BNHL
BOXNUC7i3BNHX1
BOXNUC7i3BNHX1L
BLKNUC7i3BNB

For the following SKUs add on rating label.

BOXNUC7I3BNK
BOXNUC7I3BNH
BOXNUC7I3BNKL
BOXNUC7I3BNHL
BOXNUC7i3BNHX1
BOXNUC7i3BNHX1L

For the following SKUs add on motherboard and chassis as shown below.

BOXNUC7I3BNH
BOXNUC7I3BNHL
BOXNUC7i3BNHX1
BOXNUC7i3BNHX1L

3. For all SKUs the KCC labeled wording will be corrected from "REM" to RMM".

4. For all SKUs the BN rating label will be updated with product code and wording for identification of the Serial Number and MAC address. Example below

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. This change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customers. Intel validation of a new board revision does not include testing with older versions of BIOS. This change is not expected to cause a change to the Microsoft Windows* operating system's software driver stack.

The changes to the labeling and marking have no impact on the functionality of the product. Customers should be aware of the changes and take any necessary steps to insure no impact for their receiving and processing of the product in their manufacturing.

Milestone dates are estimates and subject to change based on business and operational conditions.

Customer can expect to receive mixed inventory until current inventory levels are depleted.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change SA	Pre Change AA	Post Change SA	Post Change AA
BOXNUC7I7BNH	950951	J31153-306	J31145-305	J31153-307	J31145-306
BOXNUC7I7BNHL	950952	J57677-305	J31145-305	J57677-306	J31145-306
BOXNUC7I5BNK	950955	J31159-306	J31144-305	J31159-307	J31144-306
BOXNUC7I5BNKL	950957	J57665-305	J31144-305	J57665-306	J31144-306
BOXNUC7I5BNH	950959	J31169-306	J31144-305	J31169-307	J31144-306
BOXNUC7I5BNHL	950961	J57645-305	J31144-305	J57645-306	J31144-306
BOXNUC7I3BNK	950963	J31188-308	J22859-308	J31188-309	J22859-309
BOXNUC7I3BNKL	950965	J50876-308	J22859-308	J50876-309	J22859-309
BOXNUC7I3BNH	950967	J31191-308	J22859-308	J31191-309	J22859-309
BOXNUC7I3BNHL	950969	J50874-308	J22859-308	J50874-309	J22859-309
BLKNUC7I3BNB	955782		J22859-308		J22859-309
BLKNUC7I5BNB	955784		J31144-305		J31144-306
BLKNUC7I7BNB	955785		J31145-305		J31145-306
BOXNUC7I3BNHX1	958546	J59435-102	J22859-308	J59435-103	J22859-309
BOXNUC7I5BNHX1	958547	J59438-102	J31144-305	J59438-103	J31144-306
BOXNUC7I7BNHX1	958548	J59452-102	J31145-305	J59452-103	J31145-306
BOXNUC7I3BNHX1L	958755	J61817-304	J22859-308	J61817-305	J22859-309
BOXNUC7I5BNHX1L	958756	J61813-304	J31144-305	J61813-305	J31144-306
BOXNUC7I7BNHX1L	958757	J61751-304	J31145-305	J61751-305	J31145-306

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
August 23, 2017	00	Originally Published PCN

Product Change Notification
115772 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com
Asia Pacific/PRC Contact: apacgccb@intel.com
Europe Email: eccb@intel.com
Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2017. Other names and brands may be claimed as the property of others.

3D XPoint, Axxia, Basis, Basis Peak, BlueMoon, BunnyPeople, Celeron, Centrino, Cilk, Curie, Flexpipe, Intel, the Intel logo, Intel Atom, Intel CoFluent, Intel Core, Intel. Experience What's Inside, the Intel. Experience What's Inside logo, Intel Inside, the Intel Inside logo, Intel Insider, Intel Joule, Intel RealSense, Intel SingleDriver, Intel SpeedStep, Intel Unite, Intel vPro, Intel Xeon Phi, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Iris, Itanium, MCS, MMX, Optane, Ostro, Pali, Pentium, picoArray, Picochip, picoXcell, Puma, Quark, SMARTi, Soletta, Sound Mark, StarPro, Stay With It, the Engineering Stay With It logo, StreamSight, Tarari, The Journey Inside, Thunderbolt, the Thunderbolt logo, Transcede, True Key, Ultrabook, VTune, Xeon, X-GOLD, XMM, X-PMU and XPOSYS are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries.

Microsoft, Windows, and the Windows logo are trademarks, or registered trademarks of Microsoft Corporation in the United States and/or other countries. Java is a registered trademark of Oracle and/or its affiliates. Bluetooth is a trademark owned by its proprietor and used by Intel Corporation under license. Intel Corporation uses the Palm OS* Ready mark under license from Palm, Inc. OpenCL and the OpenCL logo are trademarks of Apple Inc. used by permission by Khronos. Learn how to use Intel Trademarks and Brands correctly at http://www.intel.com/intel/legal/tmusage2.htm.