Product Change Notification

111051 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skoool, the skoool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at http://www.intel.com/intel/legal/tmusage2.htm.

Product Change Notification

Change Notification #: **111051 - 00**

Change Title: **Intel(R) Server System SR1690WBR, PCN 111051-00, Product Design, Product Marking, Change CPU socket protective cover, Update software stack, Update Korea Certification mark**

Date of Publication: **October 17, 2011**

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 02, 2012

Description of Change to the Customer:

Intel will implement the following changes on the Intel(R) Server System SR1690WBR:

1) Changing the CPU socket protective cover to help reduce the possibility of pin damage



2) Cut in latest software stack: BIOS 57, BMC 56, FRUSDR 16, ME - no change 1.12. Customers can download the latest software package at http://www.intel.com/p/en_US/support/highlights/server/sr1690wb

3) Adding a label with the new KC mark and the manufacturing date (MMM YY) on the system board. The following is a picture of the new label:

4) Updating the Regulatory Label on the packaging box to remove the old Korea Communications Commission (KCC) mark. The following is a picture of the old Regulatory Label:

The following is a picture of the new Regulatory Label:

5) Updating the box labels on the outer product packaging to add the new Korea Certification (KC) mark. The following is a picture of the new KC mark:

6) Updating the Safety label on the chassis to replace the old KCC mark with the new KC mark. The following is a picture of the old safety Label:

The following is a picture of the new safety label

This KC mark change is for the new Korea Regulation Marking requirements on both the product and packaging box:

1. New KC mark with unique certification number to be marked
2. Human readable date information (month and year) to be marked
3. Manufacturers Name to be marked
4. Equipment Name to be marked
5. Country of Origin to be marked

Customer Impact of Change and Recommended Action:

CPU socket protective cover change has no functional impact but may require process change when inserting a CPU. Customers may want to perform some level of qualification on the new BIOS, BMC and FRUSDR software stack. Customers may need to determine the need for changing the KC marking on their products before they are exported to or sold in the Republic of Korea market.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
SR1690WBR	907330	E91167-004	E48472-311	E91167-005	E48472-312
SR1690WBRNA	905758	E91167-004	E48472-311	E91167-005	E48472-312

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
October 17, 2011	00	Originally Published PCN