



Product Change Notification

106002 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106002 - 02
Change Title: SR4850HW4 and SR6850HW4,
PCN 106002-02, Product Material,
CLASS 2: PLD code update and AND gate
change on fibre channel slot
**Reason for Revision: Remove RoHS power
supply**
Date of Publication: April 11, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 31, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Remove RoHS power supply

SR4850HW4 (SHW4UR)
877483

Change top assembly part number from C92307-009 to C92307-010
Change main board part number from C51891-603 to C51891-604
Change PLD2 to version 4.2
Change AND Gate for PCIx_RST on the Fibre Channel Module slot

SR6850HW4 (SHW6UR)
877485

Change top assembly part number from C92308-009 to C92308-010
Change main board part number from C51891-603 to C51891-604
Change PLD2 to version 4.2
Change AND Gate for PCIx_RST on the Fibre Channel Module slot

PLD2 TO 4.2:

Change to processor throttling setting when a power supplies is not
connected to AC power.

FIBRE CHANNEL MODULE SLOT:

Adjustment to the fibre channel module slot reset to improve tolerance.

Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SHW4UR	877483	877483	C92307-009	C92307-010	C51891-603	C51891-604
SHW6UR	877485	877485	C92308-009	C92308-010	C51891-603	C51891-604

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

March 3, 2006

00

Originally Published PCN

March 23, 2006

01

Add SHW6UR power supply change Change cut in date.

April 11, 2006

02

Remove RoHS power supply