



# Product Change Notification

## 107814 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107814 - 02  
**Change Title:** Intel(R) Carrier Grade Server TIGI2U, PCN 107814-02, Product Design, Incorporated Updated Platform Firmware, Reason for Revision: Update to correct TA#'s  
**Date of Publication:** December 18, 2007

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Jan 18, 2008
---	--------------

## Description of Change to the Customer:

### Reason for Revision: Update to correct TA#'s

- 1) Change BIOS Firmware from Version P10 to Version P11.
- 2) Update BMC (Baseboard Management Controller) Firmware from Version 49 to Version 53.
- 3) Change FRU/SDR (Field Replaceable Units / Sensor Data Records) Firmware from Version TJ-6.6.A to Version TJ-6.6.B.

Release notes and firmware are available from:

[http://downloadcenter.intel.com/Detail\\_Desc.aspx?ProductID=2182&DwnldID=14562](http://downloadcenter.intel.com/Detail_Desc.aspx?ProductID=2182&DwnldID=14562)

## Customer Impact of Change and Recommended Action:

Customers may want to perform re-qualification, re-test, re-certification or standard validation testing for this change.

## Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change TA	Post Change TA
TLIA2201	883851	D58988-012	D58988-013
TLID2201	883815	D58990-012	D58990-013
TLIA0201	884792	D36666-014	D36666-015
TLID0201	884854	D36669-015	D36669-016

## Reference Documents / Attachments:

Document:

Location #:

## PCN Revision History:

**Date of Revision:**

**Revision Number:**

**Reason:**

August 20, 2007

00

Originally Published PCN

December 17, 2007

01

Replace FRU/SDR Firmware TJ-6.6.A with TJ-6.6.B to fix an SDR record causing update failures.

December 18, 2007

02

Update to correct TA#'s