



Product Change Notification

103851 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 103851 - 00
Change Title: SRCU42X, PCN 103851-00, FYI, Class 2:
Update SRCU42X (Chilito2) to 4.12 firmware
release
Date of Publication: January 19, 2004

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:

Documentation
Software

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material:	Mar 19, 2004
--	--------------

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

Update factory process to include 4.12 firmware, update the Resource CD with latest versions of the Software Users Guide, update the resource cd with latest drivers and utilities including support for 64bit operating systems.

Customer Impact of Change and Recommended Action:

Customers should be aware that the firmware shipped on the controller will change and requalification may be needed at the customers discretion.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
SRCU42X	855829	855829	C48029-001	C48029-002	C47184-001	C47184-002

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:

January 19, 2004

Revision Number:

00

Reason:

Originally Published PCN