



# Product Change Notification

## 107227 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #: 107227 - 01**

**Change Title: D945PLNML, PCN 107227-01,  
Product Marking, Add RoHS label  
for PRC, Reason for Revision:  
Wrong product name in description  
of change**

**Date of Publication: February 01, 2007**

## Key Characteristics of the Change:

Product Marking

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Feb 15, 2007
---	--------------

## Description of Change to the Customer:

**Reason for Revision: Wrong product name in description of change**

Add the RoHS markings to the D945PLNM Intel Desktop Board as a requirement for the People's Republic of China for retail products manufactured on or after 1 March 2007. The markings will appear as a label on the component side of the printed circuit board and on the motherboard packaging as well.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. CDPG is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack. No expected OS image change.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change AA	Pre Change PBA	Post Change TA	Post Change AA	Post Change PBA
LAD945PLNML 876654	876654	D30497- 104	D30652- 307	D30503- 307	D30497- 105	D30652- 308	D30503- 308
BLKD945PLNML	878569	D30500-	D30652-	D30503-	D30500-	D30652-	D30503-

878569		105	307	307	106	308	308
BOXD945PLNML 878570	878570	D30501- 105	D30652- 307	D30503- 307	D30501- 106	D30652- 308	D30503- 308
OEMD945PLNML 883342	883342	D56260- 101	D56261- 303	D56262- 303	D56260- 102	D56261- 304	D56262- 304

### Reference Documents / Attachments:

**Document:**

**Location #:**

### PCN Revision History:

**Date of Revision:**

**Revision Number:**

**Reason:**

January 28, 2007

00

Originally Published PCN

February 1, 2007

01

Wrong product name in description  
of change