



Product Change Notification

112244 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2013. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #:	112244 - 00
Change Title:	Intel® Ethernet Switch FM1010 SKU FDFM1010400A MM#920977 Intel® Ethernet Switch FM2224 SKU FDFM2224F1433C MM#921370 Intel® Ethernet Switch FM4224 SKU FDFM4224F1433E MM#921415 SKU FDFM4224F1433L MM#921416 SKU EZFM4224F1433D MM#921420 Intel® Ethernet Switch FM3112 SKU FDFM3112F897C MM#922038 Intel® Ethernet Switch FM4112 SKU FDFM4112F897C MM#925684 PCN 112244-00 Product Discontinuance End of Life
Date of Publication:	August 23, 2013

Key Characteristics of the Change:
Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins:	Aug 23, 2013
Orders are Non-Cancelable and Non-Returnable After:	Aug 23, 2013
Last Product Discontinuance Order Date:	Dec 31, 2013
Last Product Discontinuance Shipment Date:	Jun 30, 2014

Description of Change to the Customer:

Intel is announcing the discontinuance of several non-RoHS versions of Intel® Ethernet Switch FM1010, Intel® Ethernet Switch FM2224, Intel® Ethernet Switch FM4224, Intel® Ethernet Switch FM3112 and Intel® Ethernet Switch FM4112 as of Aug 23, 2013. The last day for orders will be 12/31/2013. Delivery of all orders must be taken no later than 6/30/2014. See table below for replacement SKU options.

Customer Impact of Change and Recommended Action:

Customers should place their last time orders by December 31, 2013 and shipment of all orders must be taken no later than June 30, 2014.

Please contact your local Intel Field Sales Representative if you have any further questions about the Product Transition or End of Life process.

Products Affected / Intel Ordering Codes:

Marketing Name	Product Code	S-Spec	MM#	Recommended Replacement Product Code	Recommended Replacement MM#
Intel® Ethernet Switch FM1010	FDFM1010400A	S LJLB	920977	none	none
Intel® Ethernet Switch FM2224	FDFM2224F1433C	S LJLH	921370	FBFM2224F1433C	920983
Intel® Ethernet Switch FM4224	FDFM4224F1433E	S LJQP	921415	EZFM4224F1433E	930428
Intel® Ethernet Switch FM4224	FDFM4224F1433L	S LJQQ	921416	EZFM4224F1433C	930426
Intel® Ethernet Switch FM4224	EZFM4224F1433D	S LJQL	921420	EZFM4224F1433C	930426
Intel® Ethernet Switch FM3112	FDFM3112F897C	S LJSH	922038	EZFM4112F897C	930430
Intel® Ethernet Switch FM4112	FDFM4112F897C	S LJZ7	925684	EZFM4112F897C	930430

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
August 23, 2013	00	Originally Published PCN