




# Product Change Notification

## 105647 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.



Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at  
<http://www.intel.com/intel/legal/tmusage2.htm>





# Product Change Notification

**Change Notification #:** 105647 - 00  
**Change Title:** SR1475, PCN 105647-00, FYI, CLASS 2,  
DOWLING UP2, ADD WEEE MARK TO  
THE DOWLING UP2 REGULATORY  
LABEL  
**Date of Publication:** December 05, 2005

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Product Material

**Forecasted Key Milestones:**

**Description of Change to the Customer:**  
Add WEEE Mark to the regulatory label on chassis.

**Customer Impact of Change and Recommended Action:**  
Null

**Products Affected / Intel Ordering Codes:**

## System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SR1475 873809	873809	873809	D23429-001	D23429-002	D31553-001	D31553-002
SR1475NA 874472	874472	874472	D23429-001	D23429-002	D31553-001	D31553-002
SR1475NH1 873808	873808	873808	D23430-001	D23430-002	D31553-001	D31553-002
SR1475NH1NA 874473	874473	874473	D23430-001	D23430-002	D31553-001	D31553-002

## Reference Documents / Attachments:

**Document:** **Location #:**

## PCN Revision History:

**Date of Revision:** December 5, 2005  
**Revision Number:** 00  
**Reason:** Originally Published PCN

