



Product Change Notification

106837 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106837 - 00
Change Title: D946GZTSSL, PCN 106837-00, Product Material, Adds Alternate Temperature Sensor and Updates Bios
Date of Publication: October 04, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

| | |
|---|--------------|
| Date Customer Must be Ready to Receive Post-Conversion Material: | Oct 30, 2006 |
|---|--------------|

Description of Change to the Customer:

1. Add an alternative temperature sensor to the BOM to ensure part availability.
2. Update bios to version TS94610J.86A.0047 .

Customer Impact of Change and Recommended Action:

These changes have been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes on platforms received from Intel. These board changes are expected not to cause a change to the Microsoft* Windows* operating system's software driver stack.

Products Affected / Intel Ordering Codes:

| Pre Change Product Code | Pre Change MM# | Pre Change AA | Pre Change PBA | Post Change MM# | Post Change AA | Post Change PBA |
|-------------------------|----------------|---------------|----------------|-----------------|----------------|-----------------|
| BOXD946GZTSSL 882971 | 882971 | D43871-400 | D43872-400 | 882971 | D43871-401 | D43872-401 |
| BLKD946GZTSSL 882975 | 882975 | D43871-400 | D43872-400 | 882975 | D43871-401 | D43872-401 |

PCN Revision History:

| | | |
|---|-------------------------------|--|
| Date of Revision: October 4, 2006 | Revision Number: 00 | Reason: Originally Published PCN |
|---|-------------------------------|--|