



Product Change Notification

105936 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105936 - 00
Change Title: Intel® NetStructure® MPFAN0001 ATCA Fan Tray Spare Part, PCN 105936-00, Product Design, Update Fan Assembly and wiring.
Date of Publication: February 16, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:


Date Customer Must be Ready to Receive Post-Conversion Material:	Feb 17, 2006
---	--------------

Description of Change to the Customer:

The spare part Fan Tray (MPFAN0001) for the MPCHC0001 chassis was updated to include the same Fan Assemblies as the part included in assembled chassis as notified in PCN105089, including the Fan and wiring harness with twisted wiring to reduce tachometer noise.

Details listed as follows:

1. Updated fan assembly includes "twisted" wiring with shrink wrap.
2. Updating fan model to reduce tachometer noise.
3. Fan orientation will be different from previous spare parts to accommodate new wire routing.
4. Added Kapton insulated tape insulator, as shown below.



Customer Impact of Change and Recommended Action:

Change will update spare parts to reduce tachometer noise.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
MPFAN0001 849001	849001	849001	C14224-014	C14224-015		

PCN Revision History:

Date of Revision:

February 16, 2006

Revision Number:

00

Reason:

Originally Published PCN