



# Product Change Notification

## 107261 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107261 - 01  
**Change Title:** DG965GF, PCN 107261-01, Product Material, CHINA ROHS IMPLEMENTATION, UPDATE BIOS, ADD ALTERNATE SPI PART AND REPLACE VREG CONTROLLER, Reason for Revision: Wrong AA# entered for one board sku.  
**Date of Publication:** February 23, 2007

**Key Characteristics of the Change:** Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 09, 2007
<b>Date of First Availability of Post-Conversion Material:</b>	Mar 05, 2007

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

**Reason for Revision: Wrong AA# entered for one board sku.**

Add China RoHS compliance  
Updated Bios to C096510J.86A.5773 to support new SPI firmware part  
Add new SPI part for improved supply chain support  
Changed Vreg controller for improved board stability and performance

## Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. Detail BIOS release notes can be viewed from:  
<http://www.intel.com/products/motherboard/DQ965GF/tools.htm>

The Changes have been thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers.

Boards produced using the new alternate SPI part will prevent the customer from using earlier BIOS versions.

**Products Affected / Intel Ordering Codes:**

<b>Pre Change Product Code</b>	<b>Pre Change MM#</b>	<b>Pre Change AA</b>	<b>Post Change AA</b>
LADQ965GFKRA1	878118	D41019-401	D41019-402
LADQ965GFKR	878120	D41016-401	D41016-402
BLKDQ965GFEKR	878944	D41676-401	D41676-402
BOXDQ965GFEKR	878946	D41676-401	D41676-402

**PCN Revision History:**

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
February 21, 2007	00	Originally Published PCN
February 23, 2007	01	Corrected AA# for LADQ965GFKRA1.