



Product Change Notification

105667 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification 105667 - 00

#:

Change Title: SE7520BD2SCSI,
SE7520BD2V,SE7520BD2SCSID2,SE7520BD2VD2,
PCN 105667-00, FYI, Class2: SCSI cable and
bumper part number update for Pb free
compliance

Date of Publication: November 16, 2005

Type of Change Notification:

FYI - (For Your Information)

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Dec 16, 2005
---	--------------

Description of Change to the Customer:

SCSI cable and bumper part number update for Pb free compliance.

Customer Impact of Change and Recommended Action:

SCSI cables and Bumpers included in the Intel boxed boards listed below are being updated to comply with the Pb free initiative. Intel has evaluated these changes and considers these changes to have little or no customer impact. Intel is not recommending further customer evaluation of these parts.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
SE7520BD2SCSI	867507	867507	C71062-008	C71062-009		
SE7520BD2SCSID2	870783	870783	D14264-002	D14264-003		
SE7520BD2V	867817	867817	C76556-008	C76556-009		
SE7520BD2VD2	870760	870760	D14265-002	D14265-003		

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

November 16, 2005

Revision Number:

00

Reason:

Originally Published PCN