



# Product Change Notification

## 105658 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105658 - 00  
**Change Title:** SR6850HW4,  
PCN 105658-00, FYI,  
**CLASS 2: Replace the EOL DVD drive,  
Update the HSC firmware, Replace the EOL  
USB hub and Change to packaging**  
**Date of Publication:** November 14, 2005

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Product Material  
Software

## Forecasted Key Milestones:

<b>Date of First Availability of Post-Conversion Material:</b>	Nov 17, 2005
--	--------------

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

SHW6UR

MM# 874583

Change top assembly from C92308-004 to C92308-005

Change the option part number from C54930-003 to C54930-004

Replace DVD rom drive D12448-001 with D28361-001

EOL of current QSI/Philips SDR083 DVD combo drive ; switch to  
RoHS compliant DVD drive SDR089

Change the SCSI Backplane PCA number from C61492-400 to C61492-405

Replace the EOL USB hub with new part.

Update the HSC firmware from 1.05 to 1.06

Add banding material around each individual system box before  
shipping and edge protectors.

## Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

This PCN replaces 105589-0x and 105572-0x.

## Products Affected / Intel Ordering Codes:

### System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SHW6UR	874583	NA	C92308-004	C92308-005		

## Reference Documents / Attachments:

Document:

Location #:

## PCN Revision History:

Date of Revision:

November 14, 2005

Revision Number:

00

Reason:

Originally Published PCN