



Product Change Notification

108960 - 03

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108960 - 03
Change Title: Intel(R) Workstation Board S5000XVN, PCN 108960-03, Product Design, Fab Spin to Improve CPU FSB Routing, Reason for Revision: Add Intel(R) System Management Software DVD removal information
Date of Publication: December 03, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Dec 12, 2008
---	--------------

Description of Change to the Customer:

Reason for Revision: Add Intel(R) System Management Software DVD removal information

Intel is implementing a printed circuit board (PCB) change to improve the Front Side Bus (FSB) routing for the secondary processor. This design change will result in better signal quality.

For the box board products, 4-pin power cable will be removed from the box. The product code for this power cable is ASLPWRCABLE, please see Intel® Workstation Board S5000XVN Configuration Guide for order code.

Resource CD will be updated to a new version which supports Intel Deployment Assistant 2.5. Attention document is also to be updated to a new version. And CA&CROHS combination document is being added.

Intel(R) system Management Software DVD will be removed from the boxed board products.

Customer Impact of Change and Recommended Action:

No customer impact is being projected. However, standard board validation testing is recommended.

Customers needing the Intel® Active System Console, Intel® Management Packs or any of the utilities found on the Intel® System Management Software DVD, can download them from

<http://www.intel.com/go/servermanagement>.
 Customers, who would like to evaluate Microsoft* System Center Essentials, can download it from <http://www.Microsoft.com/essentials>.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
S5000XVNSASR 891986	891986	E12276-004	E11034-104	900391	E12276-201	E11034-201
S5000XVNSATAR 891999	891999	E12278-004	E11030-104	900392	E12278-201	E11030-201
BB5000XVNSASR 900393	900393	E12388-104	E11034-104	900531	E12388-201	E11034-201
BB5000XVNSATAR 900395	900395	E12391-104	E11030-104	900533	E12391-201	E11030-201

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
October 29, 2008	00	Originally Published PCN
November 26, 2008	01	Add power cable related information
December 2, 2008	02	Revise the projected date
December 3, 2008	03	Add Intel(R) System Management Software DVD removal information