



# Product Change Notification

## 106350 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106350 - 01  
**Change Title:** D101GGC, PCN 106350-01, Product Material, Northbridge chipset revision change, Reason for Revision: Correct PCN title  
**Date of Publication:** May 18, 2006

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b> May 23, 2006
--

## Description of Change to the Customer:

### Reason for Revision: Correct PCN title

The Intel Desktop Board D101GGC will change the revision of RC410 northbridge chipset from A12 to A13. This change is to add Presler CPU support.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes on platforms received from Intel. These board changes are expected not to cause a change to the Microsoft\* Windows\* operating system's software driver stack.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA
BLKD101GGCL 876341	876341	876341	D33947-307	D33947-308
BOXD101GGCL 876339	876339	876339	D33947-307	D33947-308
LAD101GGCL 876984	876984	876984	D33947-307	D33947-308
OEMD101GGCG1 882481	882481	882481	D54032-300	D54032-301

## Reference Documents / Attachments:

Document:

Location #:

## PCN Revision History:

Date of Revision:

Revision Number:

Reason:

May 18, 2006

00

Originally Published PCN

May 18, 2006

01

Correct PCN title