



Product Change Notification

107954 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107954 - 00
Change Title: Intel® Remote Management Module 2, PCN 107954-00, Product Material, Class 1: Replace A Set Of EOL Components By Equivalent Components, Update Firmware Version To 04022-5990, Update KiraTool Version To 1.5.11
Date of Publication: September 24, 2007

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Oct 19, 2007
---	--------------

Description of Change to the Customer:

A set of components are going to end of life. Those components are being replaced by equivalent components as below

- Change crystal from: EPSON 30MHz FA23H to: ARGO 30MHz AGX-3225
- Change crystal from: EPSON 12.288MHZ FA238V to: ARGO 12.288MHZ AGX-3225
- Change SDRAM from: Samsung K4S643233H-HN75 to: Micron MT48LC2M32B2B5-6
- Change EEPROM from: Atmel AT24C01A-10SU-2.7v to: Atmel AT24C01BN-SH-T
- Change ASIC from: KIRA 100R02 CPU BGA484 to: KIRA 100R02.2 ASIC BGA484 (Component name also could be marked as KIRA 100R02.2-B ASIC BGA484 due to inventory management reason)

Update firmware image version in the factory from 04022-5196 to 04022-5990

Update configuration application KiraTool version from 1.5.7 to 1.5.11

Customer Impact of Change and Recommended Action:

Customer may wish to perform testing and update their document

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre Change MM#	Post Change MM#	Pre Change TA or AA	Post Change TA or AA	Pre Change PBA	Post Change PBA
AXXRMM2	888501	894383	D84017-605	D84017-606	D84579-101	D84579-103
AXXRMM2 BULK	888498	894385	D84101-605	D84101-606	D84579-101	D84579-103

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

September 24, 2007

Revision Number:

00

Reason:

Originally Published PCN