



Product Change Notification

113126 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2014. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 113126 - 00
Change Title: Intel® Workstation System P4304CR2LFKN
PCN 113126-00, Product Design, Label
Update BIOS/ME/BMC/FRUSDR Firmware
and Labels
Date of Publication: July 14, 2014

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:


Date Customer Must be Ready to Receive Post-Conversion Material *:	Effective Immediately
---	-----------------------

** Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.*

Description of Change to the Customer:


























Intel has implemented the following change on the Intel® Workstation System P4304CR2LFKN:

1. The Intel® Workstation Board W2600CR Printed Board Assembly (PBA) revision has been updated from G21602-302 to G21602-303 with the following changes.
 - Update the BIOS from revision 01.02.2005 to 01.03.0002.
 - Update the Manageability Engine (ME) firmware from revision 02.01.05.091 to 02.01.05.107.
 - Update the Integrated Baseboard Management Controller (BMC) firmware from revision 1.00.2812 to 1.10.3560.
 - Update the FRUSDR from revision 1.03 to 1.08.
 - Remove the plastic eUSB SSD stand-off from the system accessory kit and install it on the server board, depicted below.



2. Update Regulatory Labels as follows.

- a. Common Regulatory Label: Remove the safety label IRAM, update the Canada statement and add an altitude warning in Chinese:

Pre-Change	Post-Change
<p>This device complies with Part 15 of the FCC Rules. Operation of this device is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.</p> <p>CAN ICES3(A)</p>     <p>CSA C22.2 No. 60950-1 - Electrical Safety - UL 60950-1</p> <p>この装置は、クラス A 情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。</p> <p>VCCI-A 警告使用者: 這是甲類的資訊產品，在居住的環境中使用時，可能會造成射頻干擾，在這種情況下，使用者會被要求採取某些適當的對策。</p> <p>声明 此为 A 级产品，在生活中，该产品可能会造成无线电干扰。在这种情况下，可能需要用户对其干扰采取可行的措施。</p>       <p>G19891-004</p>   	<p>This device complies with Part 15 of the FCC Rules. Operation of this device is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.</p> <p>CAN ICES-3 (A)</p>     <p>CSA C22.2 No. 60950-1 - Electrical Safety - UL 60950-1</p> <p>この装置は、クラス A 情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。</p> <p>VCCI-A 警告使用者: 這是甲類的資訊產品，在居住的環境中使用時，可能會造成射頻干擾，在這種情況下，使用者會被要求採取某些適當的對策。</p> <p>声明 此为 A 级产品，在生活中，该产品可能会造成无线电干扰。在这种情况下，可能需要用户对其干扰采取可行的措施。</p> <p>仅适用于海拔2000m以下地区安全使用。</p>      <p>Intel Corporation G19891-005</p>   

- b. Remove the safety label IRAM and update the Canada statement on the outer carton label.





R33025 001




101052








N232

この装置は、クラス A 情報技術
 装置です。この装置を家庭環境で
 使用すると電波妨害を引き起こす
 ことがあります。この場合には使
 用者が適切な対策を講ずるよう要
 求されることがあります。

VCCI-A

This device complies with Part 15 of the FCC Rules. Operation of this device is subject to the following two conditions:
 (1) This device may not cause harmful interference, and
 (2) This device must accept any interference received, including interference that may cause undesired operation.


Perchlorate Material - special handling may apply.
 See www.dtsc.ca.gov/hazardouswaste/perchlorate


G21162-004



- c. Update the AC warning label from G19902-001/002 to G84474-001. See the pictures below:

Pre-Change



WARNING:
 Apparaten skall anslutas till jordat uttag, när den ansluts till ett nätverk.
 Laite on liitettävä suojamaadoituskoskettimilla varustettuun pistorasiaan.
 Connect only to a properly earth grounded. **G19902-001**





WARNING:
 Apparaten skall anslutas till jordat uttag, när den ansluts till ett nätverk.
 Laite on liitettävä suojamaadoituskoskettimilla varustettuun pistorasiaan.
 Connect only to a properly earth grounded outlet. **G19902-002**



Post-Change


WARNING:
 Apparaten skall anslutas till jordat uttag, när den ansluts till ett nätverk.
 Laite on liitettävä suojamaadoituskoskettimilla varustettuun pistorasiaan.
 Connect only to a properly earth grounded outlet. **G84474-001**



Customer Impact of Change and Recommended Action:

This change was effective on December 20, 2013 and based on inventory levels customers will start seeing this change now.

Intel recommends that the customer perform a standard level of evaluation. Customers can download and evaluate the latest BIOS/ME/Integrated BMC and FRUSDR release notes for more information at <http://www.intel.com/support>.

Products Affected / Intel Ordering Codes:

ASMO SKU			
Product Code	MM#	Pre Change TA	Post Change TA
P4304CR2LFKN	916046	G58666-001	G58666-002

PCN Revision History:

Date of Revision:

July 14, 2014

Revision Number:

00

Reason:

Originally Published PCN