



# Product Change Notification

## 103234 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geography location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**America's Component OEM's Contact:**

Vanessa McIntyre Phone: (916) 356-4043  
Judy Schaller Phone: (916) 356-2920

Email: [vanessa.mcintyre@intel.com](mailto:vanessa.mcintyre@intel.com)  
Email: [judy.schaller@intel.com](mailto:judy.schaller@intel.com)

**America's Component Distributors Contact:** Your local account representative

**America's Boards & Systems Customers Contact:** Your local account representative

**Asia Pacific Contact:** Your local account representative

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2003. Third-party brands and names are the property of their respective owners.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 103234 - 00  
**Change Title:** Proline/2V Family, PCN 103234-00, PD,  
Product Discontinuance caused by  
component obsolescence and decreasing sales  
**Date of Publication:** April 17, 2003

**Type of Change Notification:**  
PD - (Product Discontinuance)

**Key Characteristics of the Change:**  
Product Discontinuance

## Forecasted Key Milestones:

<b>Product Discontinuance Program Support Begins:</b>	Apr 17, 2003
<b>Last Product Discontinuance Order Date:</b>	Apr 17, 2004
<b>Last Product Discontinuance Shipment Date:</b>	Jul 17, 2004

## Description of Change to the Customer:

Discontinuance of Proline/2V Products. Product Codes being retired are listed below.

## Customer Impact of Change and Recommended Action:

Please determine your remaining demand for the affected product and place orders in accordance with the key milestones listed.  
Last Product Return Date is January 17, 2004.

### Migration Plan

Short term approach (through 2003): Dialog/4, D/160SC-LS (both planned for discontinuance end of 2003 with last time buy end of 2004). These products are only be recommended when ISA to PCI transition is impossible short-term.

Long term approach: D/4PCI, D/41JCT-LS.

Contact your sales representative for additional migration information and/or any issues you may have with this Product Discontinuance Plan.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Active Products are denoted by \*

Affected Product Code	Affected MM#
PROLINE2V	838589
PROLINE2V	841042
<b>PROLINE2V</b>	<b>842055*</b>
PROLINE2VDE	838590
<b>PROLINE2VDE</b>	<b>841043*</b>
PROLINE2VIT	838592
<b>PROLINE2VIT</b>	<b>841044*</b>
PROLINE2VJP	843205
<b>PROLINE2VJP</b>	<b>846109*</b>
<b>PROLINE2VSTC</b>	<b>841921*</b>
PROLINE2VSTC	842092
PROLINE2VUK	838596
<b>PROLINE2VUK</b>	<b>841047*</b>

## Reference Documents / Attachments:

Document:

Location #:

## PCN Revision History:

Date of Revision:

Revision Number:

Reason:

April 17, 2003

00

Originally Published PCN