



Product Change Notification

Change Notification #: 119666-00

Change Title: Intel® Server System M50FCP1UR212,
PCN 119666-00, Product Design,
BIOS/BMC/ME/CPLD/FRU Firmware Update in
Factory

Date of Publication: August 31, 2023

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material*	September 16, 2023
---	--------------------

* Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.

Description of Change to the Customer:

Intel is implementing the following changes on the Intel® Server System M50FCP1UR212. Updates to the System Firmware installed at the factory are as follows:

- BIOS: R01.01.0004.factory
- BMC: 1.53-3-g2a59e1
- ME: 06.00.04.0033
- CPLD: 2.8
- FRU: 0.05

The system software update package, including the release notes for each, is available for download from <http://www.intel.com/support>. Please refer to the software release notes for a list of changes.

Note: Intel Server Boards with factory firmware will display the following message on each boot until the BIOS is updated:

"WARNING: This Server is running factory firmware. A software update is required. As part of your system integration process, please load the latest system update package (SUP) to enable the latest security, quality and performance."

Customer Impact of Change and Recommended Action:

Intel does not expect any impact to customers from these changes but encourages customers to understand the change and determine the impact on their applications. For that reason, Intel recommends that the customer perform a standard level of evaluation.

Customers can download and evaluate the latest BIOS/ BMC release notes for more information at <http://www.intel.com/support>.

Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
Intel® Server System M50FCP1UR212	M50FCP1UR212	99AN22	M60225-001, N18178-001	M36359-351, M36359-361, M36359-371	M60225-002, N18178-002	M36359-352, M36359-362, M36359-372

PCN Revision History:

Date of Revision:

August 31, 2023

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

119666-00

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com