



# Product Change Notification

## 105845 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105845 - 00  
**Change Title:** Intel NetStructure® Host Media Processing (HMP) Software Release 1.1 for Windows, PCN 105845-00, PD, Product Discontinuance caused by availability of new and improved releases  
**Date of Publication:** February 06, 2006

**Type of Change Notification:**  
PD - (Product Discontinuance)

**Key Characteristics of the Change:**  
Product Discontinuance  
Software

## Forecasted Key Milestones:

<b>Product Discontinuance Program Support Begins:</b>	Feb 06, 2006
<b>Last Product Discontinuance Order Date:</b>	Jul 01, 2007
<b>Last Product Discontinuance Shipment Date:</b>	Jul 01, 2007

## Description of Change to the Customer:

Discontinuance of Intel NetStructure® Host Media Processing (HMP) Software Release 1.1 for Windows. HMP adds major functionality and features to new major releases. Customers have a 30 month timeframe from the time of HMP 1.1's replacement, HMP 1.3, where they are still supported for customer enablement issues. Host Media Processing (HMP) Software Release 1.3 for Windows was deployed in May of 2005. For upgrade details please visit the Intel Web site listed below.

## Customer Impact of Change and Recommended Action:

End of Support of HMP 1.1 is January 1, 2008.

End of Support is defined as the date after which the following support services are no longer available:

- Telephone, email and web support for affected product(s)
  - Customers will be directed to migration product
- Active reproduction of customer-reported issues
- Installation and configuration support
- Technote and application note creation and maintenance
- Issue entry and tracking via issue management tool
- Defect entry. Fixes for unresolved defects will not be pursued nor released in Point or Service Packages, or in a product revision. All unresolved defects must be dispositioned with agreement from key stakeholders.

- Feature Request entry. All open FRs must be dispositioned with notification to key stakeholders.

**Migration Path**

Customers are requested to migrate to either Host Media Processing (HMP) Software Release 1.3 for Windows <http://www.intel.com/network/csp/products/8762web.htm> or Host Media Processing (HMP) Software Release 2.0 for Windows. <http://www.intel.com/design/telecom/products/software/hmp/8762/overview.htm>

Product Codes being retired are listed below.

Contact your sales representative for additional migration information and/or any issues you may have with this Product Discontinuance and End of Support Plan.

**Products Affected / Intel Ordering Codes:**

**Product Table**

Affected Product Code	MM#
DMIPS10C11W	868898
DMIPS10E11W	868904
DMIPS10F11W	868907
DMIPS10I11W	868905
DMIPS10R11W	868906
DMIPS10S11W	868908
DMIPS10V11W	868909

**Reference Documents / Attachments:**

<b>Document:</b>	<b>Location #:</b>
HMP 1.3	<a href="http://www.intel.com/network/csp/products/8762web.htm">http://www.intel.com/network/csp/products/8762web.htm</a>
HMP 2.0	<a href="http://www.intel.com/design/telecom/products/software/hmp/8762/overview.htm">http://www.intel.com/design/telecom/products/software/hmp/8762/overview.htm</a>

**PCN Revision History:**

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
February 6, 2006	00	Originally Published PCN