



Product Change Notification

106411 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106411 - 00
Change Title: SR1475NH1 and SR1475NH1NA, PCN 106411-00, Product Material, Class 2, System Board Replacement with version D13542-402
Date of Publication: June 09, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jun 23, 2006
---	--------------

Description of Change to the Customer:

The server baseboard is being replaced with the D13542-402 board, a 2LI label has been added to the board to indicate the PB (Lead) status of the Second Level Interconnects.

Customer Impact of Change and Recommended Action:

Evaluate when received.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SR1475NH1	880505	883558	D53640-002	D53640-005		
SR1475NH1	883558	883558	D53640-004	D53640-005		
SR1475NH1NA	883559	883559	D53640-004	D53640-005		
SR1475NH1NA	881222	883559	D53640-004	D53640-005		

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision: June 9, 2006	Revision Number: 00	Reason: Originally Published PCN
--	-------------------------------	--