



# Product Change Notification

**Change Notification #:** 119038-00  
**Change Title:** Minor Change,  
Intel® JHL8010R USB Retimer,  
Intel® JHL8010R USB Retimer,  
Intel® JHL8040R Thunderbolt™ 4 Retimer,  
Intel® JHL8040R Thunderbolt™ 4 Retimer,  
PCN 119038-00, Manufacturing Site,  
Adding Sites in Taiwan to Perform Test/Finish  
Manufacturing  
**Date of Publication:** May 12, 2022

## Key Characteristics of the Change:

Manufacturing Site

## Forecasted Key Milestones:

<b>Date of Samples Availability</b>	May 01, 2022
<b>Date of Qualification Data Availability</b>	June 01, 2022
<b>Date of First Availability of Post-Conversion Material</b>	July 01, 2022
<b>Date Customer Must be Ready to Receive Post-Conversion Material</b>	July 01, 2022

## Description of Change to the Customer:

To ensure a continuous supply of the affected products, Intel is adding manufacturing sites in Taiwan to perform the Final Test and Finish portion of the manufacturing processes. The Assembly portion of the manufacturing business will not be changed at this time.

The added Test sites are located in Taiwan and will be certified equivalent (form, fit, function, quality and reliability) for the affected products and technologies of this change.

## Customer Impact of Change and Recommended Action:

Intel considers this a Minor Change and anticipates no impact to customers for this change. There is no change to the form, fit, functionality, quality or reliability for the products. The new sites in Taiwan are certified equivalent (form, fit, function, and reliability) for the affected products and technologies of this change.

Customers may receive products tested in either existing Test site (Vietnam) or new Test sites (Taiwan). There will be no visible difference between products tested in either site.

Please contact your Intel Field Sales Representative for any additional questions or concerns.

## Products Affected/Intel Ordering Codes:

Marketing Name	MM#	Product Code	Spec Code
Intel® JHL8040R Thunderbolt™ 4 Retimer	9999H1	JHL8040R	S LMN6
Intel® JHL8040R Thunderbolt™ 4 Retimer	9999H2	JHL8040R	S LMN7
Intel® JHL8010R USB Retimer	9999HG	JHL8010R	S LMND
Intel® JHL8010R USB Retimer	9999HH	JHL8010R	S LMNE

## PCN Revision History:

**Date of Revision:**

May 12, 2022

**Revision Number:**

00

**Reason:**

Originally Published PCN



# Product Change Notification

## 119038-00

### Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at [www.intc.com](http://www.intc.com).

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)