



Product Change Notification

Change Notification #:	114072 - 00
Change Title:	Intel® QuickAssist Adapter 8920 SCC (Granite Hill) IQA89201G2P5 MM#929827 and Intel® QuickAssist Adapter 8950 SCCP (Walnut Hill) IQA89501G1P5 MM#929848, PCN 114072-00, Product Design Wake circuit enhancement
Date of Publication:	September 15, 2015

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 20, 2015
---	--------------

Description of Change to the Customer:

It has been observed that platforms with the Intel® QuickAssist Server Adapter 8920-SCC or Intel® QuickAssist Server Adapter 8950-SCCP when placed in system stand-by on system power-down would reboot when these cards were installed. Intel has root caused this symptom and are implementing a board change to correct the issue.

As a result of this change, the PBA (printed board assembly) and TA (top assembly) numbers will roll as noted in the affected products table within this PCN notice. If the PBA/TA numbers are printed on any product or box labels, those will show the PBA/TA dash roll as well.

Customer Impact of Change and Recommended Action:

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Milestone dates are estimates and subject to change based on business and operational conditions.

- The updated product has been fully tested, qualified and approved by Intel. Intel anticipates no impact to the customer.
- Intel requests customers return all unused boards via RMA for rework and replacement. Intel further recommends the replacement of installed boards displaying this issue. Work with your Intel CBA, who can help identify orders shipped after this date, to arrange return and replacement under the terms of the Intel product warranty.

To determine if you have an impacted board you can check the 2-in-1 label located on the primary side of the card for the PBA number. If the PBA is listed below, you may have an affected board.

- Intel® QuickAssist Server Adapter 8920-SCC: G81960-007
- Intel® QuickAssist Server Adapter 8950-SCCP: G98431-005



Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#	Pre Change TA	Post Change TA	Pre Change PBA	Post Change PBA
Intel® QuickAssist Adapter 8920 SCC (Granite Hill)	IQA89201G2P5	929827	G90939-003	G90939-004	G81960-007	G81960-008
Intel® QuickAssist Adapter 8950 SCCP (Walnut Hill)	IQA89501G1P5	929848	H16121-002	H16121-003	G98431-005	G98431-006

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
September 15, 2015	00	Originally Published PCN



Product Change Notification

114072 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2015. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.