



Product Change Notification

109017 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apagccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109017 - 02
Change Title: S5000VCL, PCN 109017-02, Product Design, Update BIOS to R0096, Reason for Revision: correct MM# typo
Date of Publication: September 06, 2009

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 03, 2009
---	--------------

Description of Change to the Customer:

Reason for Revision: correct MM# typo

The Intel(R) Server Board S5000VCL software is being updated to BIOS production R0096 (see BIOS release notes for details)

Customer Impact of Change and Recommended Action:

Customer to place future orders using new order code, see details in products affected table.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
BBS5000VCLSASR	896204	D69372-702	D24481-702	901626	D69372-703	D24481-703
BBS5000VCLR	896205	E14303-702	D41874-702	901627	E14303-703	D41874-703

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
January 4, 2009	00	Originally Published PCN
February 9, 2009	01	Update BIOS version and projected receive date
September 6, 2009	02	correct MM# typo