



# Product Change Notification

## 104882 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 104882 - 00  
**Change Title:** SR1400, PCN 104882-00, FYI, Class 2;  
Update System BIOS to P07  
**Date of Publication:** March 01, 2005

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Software

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 18, 2005
---	--------------

## Description of Change to the Customer:

Updating system BIOS from to P07. See BIOS P07 release notes for details.

## Customer Impact of Change and Recommended Action:

Intel anticipates no customer impact for this change. Evaluate when available.

## Products Affected / Intel Ordering Codes:

### System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SJR2USKU07	864821	864821	C79926-002	C79926-002	C53661-601	C53661-602
SR1400SYS	865571	865571	C50219-004	C50219-005	C53661-601	C53661-602

### Component Product Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SR1400SYSNA	865595	865595	C50219-004	C50219-005	C53661-601	C53661-602

## Reference Documents / Attachments:

**Document:** **Location #:**

## **PCN Revision History:**

**Date of Revision:**

March 1, 2005

**Revision Number:**

00

**Reason:**

Originally Published PCN